

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY

BREATH ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPORT

RECEIVED

								RECEIVE	D	
Com	nplete this report at the nplete this report when ain the original and ser	ever the instrum	ent is service	ed or repaired	d and wher	never it is p	olaced into s	By Carol Da ervice.	ny at 10:12 am,	Oct 03, 20
1	MASTER SN)081	NAME OF AGENCY Butler PD					10/01/201			
	TION OF INSTRUMENT (STREET N. Fulton Butler, M						TIME OF INSPE	CTION		
			-1. 11. 16.6.	11.1			8:13 pm			
	ECKLIST: Place a mark re determined.) Unmar						within estab	viisned limits.	. (Write in obser	ved values
	DIAGNOSTIC CHECK (PRINTOUT ATTACHED)			DATE AND TIME (from printout) 10/01/2014 20:13						
	COMPUTER				☑ DET	ECTOR				
	PROGRAM				☑ FILTE	ERS -				
	HEATERS SAMPL	E CHAMBER		<u>49</u> °C	☑ QUA	RTZ STAN	IDARD			
	✓ FLOW DETECTOR	ì			☑ CALIBRATION					
	PUMP HIGH SPEE	ED .			☑ PRIN	ITER				
Z	INDICATOR LIGHTS							,, ,, ,,		
	SIMULATOR SOLUTION	ON SUPPLIER (Guth Labora	atories Inc.		LOT # <u>1</u>	3010	EXP. D	ATE 01/09/20	15
V.	SIMULATOR TEMP (3	4°C ± 0.2°C)	34.0	°C SII	MULATOR	SN	SD2302	EXP. D	ATE 02/12/20	15
7 0	CALIBRATION CHECK	- (ONLY ONE	STANDARD	IS TO BE US	SED PER I	VAINTEN	ANCE REPO	DRT)		
F	CALIBRATION CHECK – (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of ,005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)									
0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE										
TES	T1 ≠ .098		TEST 2	.098			TEST 3 🖝	.099		
☑ F	PERFORM R.F.I. TEST (PRINTOUT ATTACHED)									
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)										
REF	USALS 0 (004)) 0	(.0509)	0	(.1014)	0	(.1519)	0	OVER .19	0
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS										
(USE OTHER SIDE IF NECESSARY).										
maintenance test completed sat - instrument returned to service.										
INSPECTING OFFICER SIGNATURE PRINT FULL NAME										
1	Van	Fee	CPL#3	39		Mark A. F				
TYPE I 230	ILPERMIT NUMBER/EXPIRATION 063	04/23/2				660) 679				
RETURN COMPLETED REPORT TO THE: Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office 2875 James Blvd. Poplar Bluff, MO 63901										

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI BUTLER POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 959081 10/01/14

TESTING OFFICER:
FROST
OFFICER I.D.: 39
PERMIT NUMBER: 230063
EXPIRATION DATE: 04/23/15
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

BLANK TEST	. 989	20:16
INTERNAL STANDARD	VERIFIED	20:16
EXTERNAL STANDARD	. 898	20:17
BLANK TEST	.000	20:17
EXTERNAL STANDARD	. 998	20:18
BLANK TEST	. 999	20:19
EXTERNAL STANDARD	.099	20:19
BLANK TEST	.000	20:20

N = 3 SIM. = .1 AVG. = .0983

tor Signature And CPLH39

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI BUTLER POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 950081 10/01/14 20:13

--- DIAGNOSTIC CHECK ---

COMPUTER: OKAY PROGRAM (04-07-2009): OKAY HEATERS SAMPLE CHAMBER: 49c FLOW DETECTOR: OKAY PUMP HIGH SPEED: OKAY DETECTOR: OKAY FILTERS: OKAY QUARTZ STANDARD: OKAY

PRINTER TEST

OKAY

!"#\$%%'()*+,-./0123456789:;<=>?@ABCDEFG HIJKLMNOPORSTUVWXYZ[\]^_'abcdefshijklmno parstuvwxyz{|}>+

Operator Signature

CALIBRATION:

2208-02

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI BUTLER POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 950081 10/01/14

ARREST TIME: 20:00 SUBJECT NAME: TEST/SOBER/RFI DOB: 04/23/63 SEX: M STATE/D.L.: MO/P072210009 ARRESTING OFFICER: FROST OFFICER I.D.: 39 TESTING OFFICER: FROST OFFICER L.D.: 39 PERMIT NUMBER: 230063 EXPIRATION DATE: 04/23/15 MISCELLANEOUS DATA: SOBER TEST RFI TEST

--- BREATH ANALYSIS ---

BLANK TEST	. 060	20:24
INTERMAL STANDARD	VERIFIED	20:24
SUBJECT SAMPLIE	. 000	20: 25
PANTA INTERESENCE		

Operator Signature∠

2208-0;



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 13010 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on January 14, 2013, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1218% (w/vol) ethyl alcohol. The expiration date for this lot number is January 9, 2015 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.



STATE OF MISSOURI

8²1

DEPARTMENT OF HEALTH AND SENIOR SERVICES BREATH ALCOHOL, PROGRAM



is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

DATAMASTER

ired air. Permit issued under the provisions of section	
for the determination of the alcoholic content of blood from a sample of exp	577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES LABORATORY Acting Director Gal Vertel DIRECTOR OF STATE PUBLIC HEALTH ک مح 04/23/2015 04/23/2013 230063 MO 580-0771 (6-10) NUMBER EXPIRES _ DATE

LAB-4 (R6-10)